# Oil Field Environmental Incident Summary

Responsible Party: DENBURY ONSHORE, LLC
Well Operator: DENBURY ONSHORE, LLC
Well Name: FRANKS CREEK STATE 1-23 H

Field Name: T. R. Well File #: 6551

Date Incident:3/9/2014Time Incident:12:45Facility ID Number:County:BILLINGSTwp:141Rng:101Sec:23Qtr:

Location Description: Misted area 20' by 40' just east of flare pit dike

Submitted By: Josh Cuppy Received By:

Contact Person: Josh Cuppy

5320 LEGACY DR

PLANO, TX 75024-3127

General Land Use: Badlands Terrain Affected Medium: Topsoil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident: Treater Popoff

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

1 Barrels 1 barrels

Oil 1 Barrels

Brine Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 2/17/2016 Clean Up Concluded: 5/4/2015

Risk Evaluation:

None

Areal Extent:

20'x40' area misted with oil

## Potential Environmental Impacts:

None

#### Action Taken or Planned:

Treater has been isolated and shut in until issue can be resolved. Impacted vegetation will be mowed and recovered. Impacted soils will be removed.

Wastes Disposal Location: Approved landfill

Agencies Involved:

### **Updates**

Date: 3/10/2014 Status: Inspection Author: Miller, Adam

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

# Notes:

Estimated areal extent is 100ft by 100ft. Sprayed area is on a steep side hill. Spoke with HSE coordinator on the location to discuss remediation. Advised that a burn was possible with appropriate permits and notifications. Cutting and bagging vegetation also an option. Company will contact NDDoH with plan and a re-inspection will have to take place after company actions.

Date: 3/10/2014 Status: Reviewed - Follow-up Required Author: Miller, Adam

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

Report indicates a treater popoff that was not contained. Followup is required.

Date: 5/5/2016 Status: Inspection Author: Washek, Sandi

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

Arrived on site at 2:00 p.m. Weather was sunny with wind out of the south at 15 mph. Temperature was 88 degrees F. The area of impact was located south and east of the flare. The terrain in that area is a small rise into a very steep downward slope. The hill is very well vegetated. Due to the gradient of the slope, any removal of vegetation or dirt material would cause additional issues with erosion and stabilization. This area is badlands terrain with good vegetation cover. No additional follow-up needed for site.